EWS357AP

EWS357AP Product Highlights

- Dual Concurrent 802.11ax architecture & backward-compatible with 11ac/a/b/g/n client devices
- WPA3 & WPA2-AES authentication support
- 3dBi integrated 2x2 antenna
- Supports up to 1,200Mbps in 5GHz frequency band & 574Mbps in 2.4GHz frequency band
- Local and remote management over EWS management switches & ezMaster without fees
- 1GB 802.3at PoE port for easy placement up to 328 feet from a power source
- Choice of AP, AP mesh, or mesh operation modes to meet your management & deployment requirements

EWS357AP 802.11ax, 2T2R, 574Mbps + 1200Mbps

Ix Chariot

Gigabit Switch



EWS357AP

MacBookPro
3T3R

EWS357AP 802.11ax, 2T2R, 574Mbps + 1200Mbps





EWS357AP 802.11ax, 2T2R, 574Mbps + 1200Mbps

Ix Chariot

Gigabit Switch

EWS357AP

Samsung S10+
2T2R 802.11ax

EWS357AP 802.11ax, 2T2R, 574Mbps + 1200Mbps



EWS357AP 802.11ax, 2T2R, 574Mbps + 1200Mbps





EWS357AP 802.11ax, 2T2R, 574Mbps + 1200Mbps

Ix Chariot

Gigabit Switch

EWS357AP

Pixel 3XL

EWS357AP 802.11ax, 2T2R, 574Mbps + 1200Mbps





EWS357AP 802.11ax, 2T2R, 574Mbps + 1200Mbps

Ix Chariot

Gigabit Switch

EWS357AP

Samsung S8+
2T2R 802.11ac

EWS357AP 802.11ax, 2T2R, 574Mbps + 1200Mbps

IxChariot Test - untitled1.tst

File Edit View Run Tools Window Help

Test Setup | Throughput | Transaction Rate | Response Time | Raw Data Totals | Endpoint Configuration

Group	Pair Group Name	Run Status	Timing Records Completed	Endpoint 1	Endpoint 2	Network Protocol	Service Quality	Script/Stream Filename	Pair Comment	Console knows Endpoint 1	Console Protocol	Console Serv. Qual.	Endpoint 1 knows Endpoint 2	UDP Compliant with RFC768
S8plus			**215**											
Pair 57	S8plus	Error: CHR0453	1	10.0.0.252	10.0.0.78	TCP		High_Performance_Throughput.scr		10.0.0.252	TCP	n/a	10.0.0.78	n/a
Pair 58	S8plus	Error: CHR0453	52	10.0.0.252	10.0.0.78	TCP		High_Performance_Throughput.scr		10.0.0.252	TCP	n/a	10.0.0.78	n/a
Pair 59	S8plus	Error: CHR0453	39	10.0.0.252	10.0.0.78	TCP		High_Performance_Throughput.scr		10.0.0.252	TCP	n/a	10.0.0.78	n/a
Pair 60	S8plus	Error: CHR0453	55	10.0.0.252	10.0.0.78	TCP		High_Performance_Throughput.scr		10.0.0.252	TCP	n/a	10.0.0.78	n/a
Pair 61	S8plus	Error: CHR0453	53	10.0.0.252	10.0.0.78	TCP		High_Performance_Throughput.scr		10.0.0.252	TCP	n/a	10.0.0.78	n/a
Pair 62	S8plus	Error: CHR0453	1	10.0.0.252	10.0.0.78	TCP		High_Performance_Throughput.scr		10.0.0.252	TCP	n/a	10.0.0.78	n/a
Pair 63	S8plus	Error: CHR0453	13	10.0.0.252	10.0.0.78	TCP		High_Performance_Throughput.scr		10.0.0.252	TCP	n/a	10.0.0.78	n/a
Pair 64	S8plus	Error: CHR0245	1	10.0.0.252	10.0.0.78	TCP		High_Performance_Throughput.scr		10.0.0.252	TCP	n/a	10.0.0.78	n/a



Pairs: 56 | Start: 4/16/2019, 10:11:09 PM | Ixia Configuration: | End: 4/16/2019, 10:11:38 PM | Run time: 00:00:29 | Error detected

Thank you.

N.V.K. Inter Co.,Ltd.